

State of Utah

DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Report Date: September 29, 2006

Supervisor DDJ

Mine Name: Vermillion Mine

Operator Name: Color Country Rock Preston Hafen 115 South Main

Veyo, Utah 84782

Inspector(s): Doug Jensen

Other Participants: Rulon Jessop- CPI

Mine Status: Active

Permit number: S/053/076 Date: September 13, 2006

Time: 12:30 PM

Weather: Clear, Warm

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads,			
highwalls, shafts, drill holes)			
8. Water Impoundments			
9. Soils			
10. Revegetation			
11. Air Quality			
12. Other		П	П

Purpose of Inspection:

Check progress of the mining activity at the site.

Directions to Site:

See previous inspection report.

Inspection Summary:

CPI was operating at the site removing large boulders. There was a loader, trackhoe and several trucks operating at the site. The rocks were being hauled to St. George.

The area being disturbed was an area in addition to the areas that I gps'd in March of this year. The new disturbance will add about a half an acre to the total disturbance at the site. I did not gps the additional disturbance but will do so during my next visit. Pictures were taken at the site.

Conclusions and Recommendations:

I will continue to monitor the site when I am in the area.

Inspector's Signature Leavy Jensen Date: 9/28/06


dj:pb


cc:

Color Country Rock

Russ Schreiner, BLM, St George FO UTU-80887

O:\M053-Washington\S0530076-Vermillion\inspections\09132006insp.doc





2006/09/13 12: Inspections 084.jpg